

Product Safety Recall

75-150hp FourStroke Shift Link Retainer Installation

Models Covered	Serial Range
75-115hp 4S, SeaPro, Prox XS	2B095049 – 3B633935
135-150hp 4S, SeaPro, Pro XS	1B905505 – 3B625824

Dates sold: 2011 to 2025

Identification Pictures

75-115hp 4S	135hp 4S	150hp 4S	Pro XS	SeaPro
				

Defect:

A stud located on the upper shift shaft arm on above models may corrode if the engine is used in Saltwater. If that happens, there may be a loss of shift function

Hazard: Potential loss of shift control of the boat's propulsion system.

What to do:

1. Consumers with affected products should contact their Mercury Dealer to arrange for a rectification to be performed and return the engine to dealer every 100 hours for regreasing.
2. Consumers should not use their boat until the rectification has been performed.
3. Send us an email or phone us if you are unable to return the product or have sold it to another person

Contact details:

For more information contact Marine Power International at merc.info@mercmarine.com