

Product Safety Recall

450R & 500R V8 Racing Outboard Top Cowl Bezel Assy

| Models Covered | Serial Range |
|----------------|---------------------|
| 450R | 1E083006 – 1E099696 |
| 500R | 1E099432 – 1E102508 |

Identification Pictures



Defect: The air vents of the affected engine cover may allow for fingers to be placed through the air vent gaps.

Hazard: There is a risk of serious injury including amputation or lacerations to fingers if placed through the air vents. Injuries have occurred because of this hazard.

What to do:

1. Consumers with affected products should contact their Mercury dealer to arrange for a bezel assembly to be installed over the air vents.
2. Send us an email or phone us if you are unable to return the product or have sold or gifted it to another person

Contact details: For more information contact Marine Power International on +61 3 9791 5822 or email merc.info@mercmarine.com