

Product Safety Recall

V6, V8 and V8R Outboards Top Cowl Assembly

Models Covered	Serial Range
V8 200–300 and V6 175–225 FourStroke, Pro XS®, SeaPro™, and Verado® Models	V8 2B529482 – 3B430915
	V6 2B529482 - 3B421321
V8 250R, V8 300R and 300R HD Models	1E080500 - 1E091195
	2B529482 – 3B430915

Engine Identification Pictures



Do you own this product?

Affected Marine Outboard engines:

- V8 200–300 HP and V6 175–225 HP FourStroke, Pro XS®, SeaPro™ and Verado® Model outboard engines

- V8 250R, V8 300R and 300R HD Model outboard engines

Dates sold: 1 September 2018 – 25 October 2023



Defect: The air vents of the affected engine cover may allow for fingers to be placed through the air vent gaps.

Hazard: There is a risk of serious injury including amputation or lacerations to fingers if placed through the air vents. Injuries have occurred because of this hazard.

What to do:

1. Always keep fingers away from the air vents on the engine. Do not use the air vents as a handhold when boarding or departing the boat.
2. If your cowl does not have two silver coloured bezel assembly currently installed, please contact your local Mercury Marine Authorized Outboard Dealer to arrange for these to be fitted over the air vents. This will be done at no cost to you.

Contact details: Contact Mercury Marine Customer Service on +61 3 9791 5822 (Monday to Friday, 8.30am to 4.30pm AEST) or email merc.info@mercmarine.com

To locate your nearest Mercury Marine dealer, <https://www.mercurymarine.com/en/nz/find-a-dealer/>

See www.recalls.govt.nz for other New Zealand consumer product recalls