



# Product Safety Recall

Do you own this Product	
Models Covered	Serial Number
All helm systems with Gen 2 DTS controls	N/A
All helm systems with Avator controls	N/A

## Gen 2 DTS Controls



## Avator Controls



**Why the product is recalled:** GEN 2 or Avator Controls fitted to Boats manufactured prior to June 2025 may malfunction.



**Hazard:** If a malfunction occurs, a horn will sound and gear changes may become disabled and engine power may be limited. This loss of function could potentially cause a collision or result in the boat becoming stranded.



1. Consumers with GEN 2 DTS or Avator Controls installed should contact their Mercury dealer to arrange to have the Control rectified.
2. Consumers should not use their boat until this rectification has been performed.
3. Send us an email us if you are unable to return the product or have sold or gifted it to another person



For more information contact Marine Power International on 03 9791 5822 or email [merc.info@mercmarine.com](mailto:merc.info@mercmarine.com)

See [productsafety.gov.au](http://productsafety.gov.au) for Australian product recall information