



Product Safety Recall

Do you own this Product	
Models Covered	Serial Number
All helm systems with Gen 2 DTS controls	N/A
All helm systems with Avator controls	N/A

Gen 2 DTS Controls



Avator Controls



Why the product is recalled: GEN 2 or Avator Controls fitted to Boats manufactured prior to February 2025 may fault when operating the boat



Hazard: While using Gen 2 DTS or Avator controls, lever faults may occur. These faults usually occur while operating in reverse and near mid to wide-open throttle.



1. Consumers with GEN 2 DTS or Avator Controls installed should contact their Mercury dealer to have the lever adapt performed if applicable
2. Send us an email us if you are unable to return the product or have sold or gifted it to another person



For more information contact Marine Power International at merc.info@mercmarine.com

See productsafety.gov.au for Australian product recall information